



Luca Molinari, MSc
Innse Berardi COO



Ferdinando Cannella, PhD
Industrial Robotics Facility
Coordinator



Autonomous Robot System for Monitoring and Cleaning of Bridges



brought to you by euROBOTICS
Rotterdam (NL) 2022



Bologna (Italy) 2022



Autonomous Robot System for Monitoring and Cleaning of Bridges

Opened: September 4, 1967 (**Construction started:** 1963)

Total length: 1,012 m, (0.629 mi)

Width: 18 m (59 ft)

Height: Piers 90 metres (300 ft), Road Deck 45 metres (148 ft)

Engineer: Riccardo Morandi

Morandi's bridge collapse



Morandi's Bridge before and after the collapse of the Pillar 9
(14th August 2018 at 11:36am with 43 victims and 16 injuries)

Autonomous Robot System for Monitoring and Cleaning of Bridges

Opened: August 4, 2020 (**Construction started:** June 25, 2019)

Total length: 1,067 m, (0.663 mi)

Width: 31 m (103 ft)

Height: Piers 45 metres (150 ft), Road Deck 50 metres (151 ft)

Architect: Renzo Piano

San Giorgio's bridge building









Very Efficiency in Building: <24 months!







High Tech Structure: >240 sensors!!!

“Simple but not trivial. A steel bridge, safe and durable. Because bridges do not have to collapse.”
[Renzo Piano]

Autonomous Robot System for Monitoring and Cleaning of Bridges



Autonomous Robot System for Monitoring and Cleaning of Bridges



Autonomous Robot System for Monitoring and Cleaning of Bridges

Traditional bridge inspections

- Time consuming
- Dangerous
- Expensive
- Imprecise
- Imperfect record keeping
- Lack of comparison data to previous year

Advanced bridge inspections



(ALMOST) NO MONITORING!!!



<https://www.youtube.com/watch?v=-LmAcL2WFFo>




<https://www.flyability.com/articles-and-media/drones-bridge-inspection>

- Inspection road and highway damage due to environmental impact and natural erosion.
- Maintain bridges, tunnels and other critical infrastructure to help reduce the cost of on-demand maintenance. Perform railway inspections frequently and efficiently to avoid damage and derailment.
- View seaports, canals, and waterways in superior detail and accuracy.
- Faster Inspection
- No road partial/total closure and traffic issues
- Repeatability is not guaranteed and then there will be lack of comparison with data to previous years.

Autonomous Robot System for Monitoring and Cleaning of Bridges



NEEDS AN OPERATOR!!!



Autonomous Robot System for Monitoring and Cleaning of Bridges

High Tech Structure!!!!



**Monitoring and Maintenance Robotic System for San Giorgio Bridge
(Genoa, Italy)**

Partners



UNIVERSITÀ
POLITECNICA
DELLE MARCHE





Monitoring and Maintenance Robotic System for San Giorgio Bridge (Genoa, Italy)

<https://www.youtube.com/watch?v=WmQ1bQNgKds>

Monitoring and Maintenance Robotic System for San Giorgio Bridge

MECHATRONICS




Monitoring:

- Underside of the deck
- Head of piers

Maintenance:

- Sound barriers
- Solar panels



Contact: first tentative for a fully autonomous I&M robot to interact with the environment

- Sensors (ultra-sound, magneto-scope, etc.)
- Brushes for cleaning

Cognitive Mechatronics: be aware about the environmental parameters in order to make decisions

- Autonomy: batteries management
- Navigation: trajectories planner
- Self-Diagnosis: fault management

Monitoring

San Giorgio Bridge (Genoa): Robots Structures




Cognitive Mechatronics

MODELLING OF KINEMATICS AND DYNAMICS OF THE ROBOT

Robots Structures

Robot Monitoring



Monitoring

andrea.pantaloni@ubisive.it ESCI

CONDIZIONI DI AVVIO COMANDI ROBOT CPS ARCHIVIO ISPEZIONI ULTIMA ISPEZIONE LOG MESSAGGI WEBCAM



ROBOT INSPECTION NORD

Chiudi Tutto

ASSE Z

- Posizione Attuale Asse Z: 0.0000 m
- Asse Z Bloccato: NO
- Sensore di Distanza Anteriore: 0.00 mm
- Sensore di Distanza Posteriore: 0.00 mm
- Velocità: 0.00 mm/s

ASSE X

- Posizione Attuale Asse X: 6.0000 m
- Asse X Bloccato: NO
- Beam Arretrata: NO
- Sensore di Distanza dall'Impalcato: 0.00 mm
- Beam: Distanza Pilone Successivo: 0.00 mm
- Beam: Distanza Pilone Precedente: 0.00 mm
- Beam: Distanza dal Pilone: 0.00 mm
- Velocità: 0.00 mm/s

ROBOT

- In Stazione Home: NO
- In Stazione Home, Blocco Meccanico Attivato: NO
- Sensore di presenza Pinna: 0.00 mm
- Premuto stop di emergenza: NO

BATTERIE

- Batteria in carica: NO
- Livello di carica totale pacco batterie: 100.0 %

Mostra variabili secondarie



CICLO

- Ispezione in Corso: NO
- Ispezione Completata: NO
- Sezione attuale d'ispezione: 0
- Posizione del Beam per acquisizione: 0
- Robot fermo e bloccato per acquisizione: NO
- Ritorno alla posizione Home in corso: NO


CONSENSI

UBISIVE

CHANGE DETECTION



Monitoring




The vision will be moved by the sliding beam and the images will be processed with Pattern Analysis in order to detect potential «anomalies» that will be reported to the human operators.

The surface Monitoring will investigate:

- 1) Painting degrading
- 2) Corrosion of metallic parts
- 3) Joint status
- 4) Welded status
- 5) Crack detection

Monitoring of the evolution along the months and years!



Monitoring

FULLY AUTONOMOUS Robot for inspecting the Genova San Giorgio bridge




Weight: **2400 kg**
(arm: 300kg of carbon fiber structure)

Payload of the arm:
On the tip: **80 kg**
Distributed: **250 kg**

Size:
Arm length: **11+6 m**
Length: **7 m**
High: **10 m**

Speed: **0.15 m/s**
Span: **1100 m**

+/- 25mm vibrations



The RESULTS


Results

FIRST DEFECT DETECTION (2021, February)



The first scanning the whole bridge was covered and more than 30000 pictures were taken. A couple of them are shown in the following. **THIS IS THE BRIDGE PATTERN «REFERENCE»**


Not defects DETECTED by the algorithm, because the bridge was new!



Not defects DETECTED by the algorithm, because the bridge was new!

Results

SECOND DEFECT DETECTION (2022, July)



Considering the bridge was detected just 1.5 year before, none was expeting any defect, an overall check up was carried on on the robots and only **the cameras were tested around the robot parking areas** with the artificial markers in order to check their functionalities after 18 months without being used.


Results

THIRD DEFECT DETECTION (2023, December)



The third inspection involved almost half bridge with around 1000 pictures (statistically determined) to assess where some defects were coming out: considering that only some dirty areas were found, the captured pictures were drastically reduced compared to 30000 for scanning the whole bridge.


Evident dirt zone EASILY DETECTED by the algorithm



Not Evident dirt zone NOT EASILY DETECTED by the algorithm (the ML needs to be trained about the dust and similar defects)


Results

FOURTH DEFECT DETECTION (202?, ???)



????

????





???

Inspection and Maintenance Robotic System for San Giorgio Bridge

Wash

The transversal movement compensates the structure misalignments (rails, glasses, floor, etc.)



**Thank you
for the
attention!**



Luca Molinari

COO InnSE Berardi, Camozzi Group

lmolinari@innse-berardi.com